IEEE Xplore

Thu, 16 Nov 2006, 9:21:28 AM EST

Search Query Display

Recent Search Queries Results

- #1 ((laser <near/2> trim* <and> measure <near/2> voltage)<in>metadata) 0
- #2 ((laser <near/2> trim* <and> detect <near/2> voltage)<in>metadata) 0
- #3 ((trim* <and> detect <near/2> voltage)<in>metadata) 0
- #4 ((trim* <and> detect* <near/2> voltage)<in>metadata) 2
- #5 ((trim* <and> measur* <near/2> voltage)<in>metadata) 6

hlw

Page 1 of 1

Application	No.:	1081	1357
--------------------	------	------	------

15 BRS	S1	(blow or burn or cut or trim) near3 link same (measure\$1 or measuring or measurement or detect\$2 or detecting or	US-PGPUB; USPAT;	16-Nov-06
		detection) near2 voltage	EPO; JPO;	
202 BRS	S2	(blow or burn or cut or trim) near3 fuse same (measure\$1 or measuring or measurement or detect\$2 or detecting or	US-PGPUB; USPAT;	16-Nov-06
		detection) near2 voltage	EPO; JPO;	
25 BRS	S4	S3 and (fuse\$1 or link\$1)	US-PGPUB; USPAT; EPO; JPO;	16-Nov-06
42 BRS	S5	S3 and (fusible or trim\$4)	US-PGPUB;	16-Nov-06
		(USPAT;	
			EPO; JPO;	
114 BRS	S8	S6 and (fusible or trim\$4)	US-PGPUB;	16-Nov-06
			USPAT;	
			EPO; JPO;	
703 BRS	S3	338/92,185,196,198,288,289.ccls.	US-PGPUB;	16-Nov-06
			USPAT;	
			EPO; JPO;	
621 BRS	S6	341/121,154.ccls.	US-PGPUB;	16-Nov-06
			USPAT;	
			EPO; JPO;	40.11 00
45 BRS	S 7	S6 and (fuse\$1 or link\$1)	US-PGPUB;	16-Nov-06
> ,			USPAT; EPO; JPO;	
000 DD0	00	222/207 202	US-PGPUB:	16-Nov-06
223 BRS	S9	323/297,298.ccls.	USPAT;	10-1107-00
			EPO; JPO;	
7 BRS	S10	S9 and (fuse\$1 or link\$1)	US-PGPUB;	16-Nov-06
7 5110	010	os and (laseur of linkur)	USPAT;	10 1101 00
			EPO; JPO;	
9 BRS	S11	S9 and (fusible or trim\$4)	US-PGPUB;	16-Nov-06
5 2.15			USPAT;	
			EPO; JPO;	
521 BRS	S12	327/525.ccls.	US-PGPUB;	16-Nov-06
			USPAT;	
			EPO; JPO;	
281 BRS	S13	diode near5 (fuse or fusible or link) near5 parallel	US-PGPUB;	16-Nov-06
			USPAT;	
•		•	EPO; JPO;	